

# Fan Modification

---

A modification was made to the Detector Head Assembly to avoid oil ingress through the Fan Assembly into the body of the Detector Head.


This change was for all new Detector Heads with serial numbers greater than those below:

OMD6 13293331

OMD7 71329701

Since all customer returns have also now been upgraded to current revision, there will be older units in the field fitted with new fans.

Therefore the best way to check which replacement fan the customer needs is to check the number of fixing screws (See images below).



Single Screw Version  
(P/N D5622-005-02)

Two Screw Version  
(P/N 53569-K005)